



Instructions/Attach To:

#SBUSCN181

Date: 09/06/12

Page: 1 of 1

From: Product Service Department  
Concerning: Gas Pressure Washer Pump Change  
Distribution: All Authorized Service Centers

This bulletin is to make you aware of a pump change that affects older model vertical gas pressure washers beginning in the below model numbers:

- PW1549
- PW1650
- PW1749
- PW1750
- PW1753
- PW1755
- PW1850
- PW2030
- PW2050
- PW2200

This will affect any other units that have a Briggs & Stratton or Tecumseh engine.

Pump part number PM343501SJ that would work on these units has now been replaced.

The new pump part number to replace this is PM351370SJ and this new pump will **NOT** work on these older units. There are no conversion kits available for this new pump.

Any of the newer vertical pump pressure washers with Honda engines can use the new pump PM351370SJ.

Any questions regarding how to do this, please contact the Pressure Washer Technical Support line at 1-800-330-0712.